

<u>1 CHAPTER 1. INTRODUCTION</u>	1
<u>1.1 Project Aim</u>	1
<u>1.2 Background to Study</u>	1
<u>1.3 Introduction to Composite Materials</u>	4
<u>1.4 Composite Concerns</u>	5
<u>1.5 Thermoplastic Usage</u>	5
1.6. Commercial PES-Based Co-Polymer	6
<u>1.7 Thermoplastic Dissolved Thermosets</u>	7
<u>1.8 Lightning Strikes</u>	8
<u>1.9 Current Production</u>	10
<u>1.10 Nanographite</u>	11
<u>1.10.1 Introduction</u>	11
<u>1.10.2 Nanographite Structure</u>	13
<u>1.10.3 Exfoliation of Graphite</u>	13
<u>1.10.4 Polymerisation</u>	16
<u>1.11 Carbon Nanotubes</u>	16
<u>1.11.1 Introduction</u>	16
<u>1.11.2 Nanotube Structure</u>	17
<u>1.11.3 Nanotube Properties</u>	21
<u>1.11.4 Practical Considerations</u>	21
<u>1.11.5 Synthesis</u>	22
<u>1.11.6 Growth Mechanisms</u>	23
<u>1.11.7 Functionalisation</u>	24
<u>1.11.8 Nanotubes in Polymers</u>	26
<u>1.12 Polypyrrole; An Intrinsically Conducting Polymer</u>	27
<u>1.13 Carbon Fibre</u>	28
<u>1.14 Project Objectives</u>	Error! Bookmark not defined.
<u>1.15 References</u>	Error! Bookmark not defined.
<u>CHAPTER 2. CRYSTALLIZATION – THEORY AND EXPERIMENT</u>	39
<u>2-1 Avrami Model</u>	39

<u>2-2 Non-Isothermal Crystallisation</u>	42
<u>2-2-1 Modified Avrami Model</u>	43
<u>2-2-2 Ozawa Model</u>	44
<u>2-2-3 Combined Ozawa/Avrami Model</u>	46
<u>2-3 Experimental</u>	47
<u>2-3-1 Materials</u>	47
<u>2-3-2 Synthesis of PEEK (synthesis was carried out by Cytec)</u>	47
<u>2-3-3 Additional Note</u>	48
<u>2-3-4 DSC</u>	48
<u>2-3-4-1 Isothermal Crystallization</u>	48
<u>2-3-4-2 Non-isothermal Crystallization</u>	48
<u>2-4 References</u>	Error! Bookmark not defined.

CHAPTER 3. CRYSTALLIZATION – RESULTS AND DISCUSSION
.....ERROR! BOOKMARK NOT DEFINED.

<u>3-1 Introduction</u>	51
<u>3-2 Materials</u>	Error! Bookmark not defined.
<u>3-3 An initial Note on Errors</u>	Error! Bookmark not defined.
<u>3-4 Results</u>	52
<u>3-4-1 Isothermal Studies</u>	52
<u>3-4-1-1 Avrami Analysis</u>	57
<u>3-4-1-2 Melting Behaviour Following Isothermal Crystallization</u>	60
<u>3-4-2 Non-Isothermal Results</u>	64
<u>3-4-2-1 Crystallization Behaviour</u>	64
<u>3-4-2-2 Melting Behaviour Following Non-Isothermal Crystallisation</u>	68
<u>3-4-2-3 Modified Avrami Model</u>	76
<u>3-4-2-4 Ozawa Analysis</u>	79
<u>3-4-2-5 Combined Ozawa/Avrami Model</u>	81
<u>3-4-2-6 Maximum Rate of Crystallization</u>	83
<u>3-5 Conclusions</u>	85
<u>3-6 References</u>	87

CHAPTER 4. RHEOLOGY THEORY AND EXPERIMENTAL **89**

<u>4-1 Introduction</u>	89
<u>4-2 Theory</u>	90
<u>4-3 Oscillatory Rheometry</u>	93

<u>4-4 Experimental</u>	96
<u>4-4-1 Polymerisation of PES-Based Co-Polymer</u>	96
<u>4-4-2 Formation of PEES Unit</u>	Error! Bookmark not defined.
<u>4-4-3 Formation of PES Unit</u>	97
<u>4-4-4 Radel A-100</u>	98
<u>4-4-5 Rheology</u>	98

4-5 ReferencesError! Bookmark not defined.

CHAPTER 5. RHEOLOGY OF MATRIX, AND FILLED CONDUCTING COMPOSITE MATERIALSERROR! BOOKMARK NOT DEFINED.

5-1 Introduction to Chapter.....Error! Bookmark not defined.

5-2 Materials.....Error! Bookmark not defined.

5-3 Results.....Error! Bookmark not defined.

<u>5-3-1 Strain / Stress sweeps</u>	Error! Bookmark not defined.
<u>5-3-2 Sampling</u>	Error! Bookmark not defined.
<u>5-3-3 Frequency Sweeps</u>	Error! Bookmark not defined.
<u>5-3-4 Time Study</u>	Error! Bookmark not defined.
<u>5-3-5 Flow Studies</u>	Error! Bookmark not defined.
<u>5-3-6 Creep</u>	Error! Bookmark not defined.

5-4 Conclusions

5-5 References

CHAPTER 6 CONDUCTIVITY THEORY AND EXPERIMENT..... ERROR! BOOKMARK NOT DEFINED.

6-1 Materials.....Error! Bookmark not defined.

6-2 Experimental Methods.....Error! Bookmark not defined.

6-3 Experimental and Theory.....Error! Bookmark not defined.

<u>6-3-1 Polypyrrole Synthesis</u>	Error! Bookmark not defined.
<u>6-3-2 Conductivity</u>	Error! Bookmark not defined.
<u>6-3-2-1 Percolation</u>	Error! Bookmark not defined.
<u>6-3-2-2 Resistance and Conduction</u>	Error! Bookmark not defined.
<u>6-3-2-3 Four-Point Probe Technique</u>	Error! Bookmark not defined.
<u>6-3-2-4 Conductivity of polypyrrole</u>	Error! Bookmark not defined.
<u>6-3-2-5 Conductivity of Carbon fibre</u>	Error! Bookmark not defined.
<u>6-3-3 Doping</u>	152
<u>6-3-3-1 Polypyrrole doping</u>	Error! Bookmark not defined.
<u>6-3-3-2 Carbon Fibre doping</u>	Error! Bookmark not defined.

<u>6-3-4 In-situ Polymerisation of Nanographite/PES-Based Co-Polymer (polymerization was carried out by Cytec)</u>	Error! Bookmark not defined.
<u>6-3-5 Sonication of nanographite</u>	Error! Bookmark not defined.
<u>6-3-6 Synthesis of PEEK</u>	Error! Bookmark not defined.
<u>6-3-7 Synthesis of PEKK</u>	Error! Bookmark not defined.
<u>6-3-8 Preparation of Epoxy Resin</u>	Error! Bookmark not defined.
<u>6-3-9 Hot-Stage Microscopy for Fibre Dissolution</u>	Error! Bookmark not defined.
<u>6-3-10 Solution Blending and Direct Blending</u>	Error! Bookmark not defined.
6-3-10-1 Solution Blending	Error! Bookmark not defined.
6-3-10-2 Direct Blending	Error! Bookmark not defined.
6-3-10-2-1 PES Based Co-Polymer and Nanographite	Error! Bookmark not defined.
6-3-10-2-2 Nanographite + Carbon Nanotubes	Error! Bookmark not defined.
6-3-10-2-3 Nanographite and Carbon Black	Error! Bookmark not defined.
6-3-10-2-4 Nanographite and Phthalocyanine ...	Error! Bookmark not defined.
6-3-10-2-5 Nanographite and TTF TCNQ	Error! Bookmark not defined.
<u>6-3-11 Extrusion</u>	Error! Bookmark not defined.
6-3-11-1 Theory	Error! Bookmark not defined.
6-3-11-2 Experimental	Error! Bookmark not defined.
<u>6-3-12 Plasti-Corder[®]</u>	Error! Bookmark not defined.
6-3-12-1 Theory	Error! Bookmark not defined.
6-3-12-2 Experimental	Error! Bookmark not defined.
<u>6-3-13 Laboratory Scale Melt-Spinning</u>	Error! Bookmark not defined.
<u>6-3-14 Scanning Electron Microscopy –SEM</u>	Error! Bookmark not defined.
6-3-14-1 Theory	Error! Bookmark not defined.
6-3-14-2 Experimental	Error! Bookmark not defined.
<u>6-3-15 Thermal Gravimetric Analysis –TGA</u>	Error! Bookmark not defined.
6-3-15-1 Theory	Error! Bookmark not defined.
6-3-15-2 Experimental	Error! Bookmark not defined.
<u>6-3-16 Differential Scanning Calorimetry – DSC</u>	Error! Bookmark not defined.
6-3-16-1 Theory	Error! Bookmark not defined.
6-3-16-2 Experimental	Error! Bookmark not defined.
<u>6-3-17 Density</u>	Error! Bookmark not defined.
6-3-17-1 Theory	Error! Bookmark not defined.
6-3-17-2 Experimental	Error! Bookmark not defined.

6-4 References

CHAPTER 7 CONDUCTIVITY RESULTS AND DISCUSSION

7-1 Introduction

7-2 Materials and Experimental Methods

7-3 Results and Discussion

<u>7-3-1 Polypyrrole and Carbon Fibre</u>	Error! Bookmark not defined.
<u>7-3-1-1 Electrochemically Synthesised Polypyrrole Films</u>	Error! Bookmark not defined.
7-3-1-2 Polypyrrole powder purchased from Aldrich	Error! Bookmark not defined.
7-3-1-3 Polypyrrole purchased from BASF	Error! Bookmark not defined.
<u>7-3-1-4 Carbon Fibre</u>	Error! Bookmark not defined.
<u>7-3-2 Doping</u>	Error! Bookmark not defined.
<u>7-3-2-1 Electrochemically Synthesised Polypyrrole</u>	Error! Bookmark not defined.
<u>7-3-2-2 Polypyrrole powder purchased from Aldrich</u>	Error! Bookmark not defined.
<u>7-3-2-3 Polypyrrole Purchased from BASF</u>	Error! Bookmark not defined.
7-3-2-4 BASF Film Thickness and Mass Before and After Acid Exposure	Error! Bookmark not defined.
<u>7-3-2-5 BASF polypyrrole doped with Alkali</u>	Error! Bookmark not defined.
<u>7-3-2-6 Carbon Fibre</u>	Error! Bookmark not defined.
<u>7-3-2-7 Rationalisation of Doping Results</u>	Error! Bookmark not defined.
<u>7-3-3 Nanomaterial results</u>	Error! Bookmark not defined.
<u>7-3-3-1 An initial note on errors</u>	Error! Bookmark not defined.
<u>7-3-3-2 Solution Blending</u>	Error! Bookmark not defined.
<u>7-3-3-3 In-situ Processing</u>	Error! Bookmark not defined.
7-3-3-4 Direct Blending	193
7-3-3-4-1 Nanographite Blended with PES-Based Co-Polymer	198
<u>7-3-3-4-2 Nanographite Blended with Carbon Nanotubes</u>	194
<u>7-3-3-4-3 Carbon Black</u>	Error! Bookmark not defined.
7-3-3-4-4 Nanographite Blended with Phthalocyanine	197
7-3-3-4-5 TTF TCNQ	199
<u>7-3-3-5 Epoxy</u>	Error! Bookmark not defined.
<u>7-3-3-6 TGA</u>	Error! Bookmark not defined.
<u>7-3-3-7 DSC</u>	Error! Bookmark not defined.
<u>7-3-3-8 SEM</u>	Error! Bookmark not defined.
7-3-3-9 Extrusion	218
7-3-3-10 Plasti-Corder®	222
7-3-3-11 Hot-Stage Microscopy	225
7-3-3-12 Laboratory Scale Melt-Spinning	229
7-3-3-13 PEEK and PEKK	229
7-3-3-14 % Carbon Present	235
7-3-3-15 Specific Gravity Measurements	237
7-3-3-15-1 Density	237
 <u>7-4 Conclusions</u>	 239

7-5 References.....	242
Appendix 1 – Correction factors used in four-point probe.....	243
Appendix 2 – Error calculations.....	245
CHAPTER 8 CONCLUSIONS.....	247
9 FURTHER WORK.....	251